



Image 1: Traveling southbound from Hwy 64. Truck is cresting the hill.



Image 2: Traveling southbound uphill, continues uphill and curves to the right.



Image 3: Traveling southbound uphill, curves sharply to the right.



Image 4: Traveling southbound uphill, entrance of landfill to the right on crest of hill.




Image 5: View northward uphill, entrance of landfill to the left.

23ft ditch to ditch - 18ft travel portion



Image 6: Traveling southbound, steep downhill, just after landfill entrance, sharp curve to the left.



Image 7: Traveling southbound, continuing sharp curve to the left seen in image 6.



Image 8: Traveling southbound, after sharp curve to the left hill crest just ahead and veers right



Image 9: Traveling southbound, on crest of hill steep hill veering left toward entrance of NorthShore Rd on the right.



Image 10: Traveling southbound, entrance of NorthShore Rd on the right. Road curves to the left.



Image 11: Traveling southbound, toward entrance of West Nipissing public beach.



Image 12: Traveling southbound, entrance of West Nipissing public beach on right. Short steep hill ahead veers right.




Image 13: Traveling southbound, on crest of hill seen in image 12. Curves to the right towards numerous residential driveways.



Image 14: Traveling southbound, curves sharp to the left at residential driveway.



Image 15: Traveling southbound, downhill, curves sharp to the right at residential driveway.



Image 16: Traveling southbound, uphill, curves sharp to the left at residential driveway.



Image 17: Traveling southbound, hill curves sharp to the left at residential driveway.



Image 18: Traveling southbound, hill crests with sharp curve to the left. Beginning of 60 km zone.



Image 19: Traveling southbound, on hill crest seen in image 18 with sharper curve to the left.



Image 20: Traveling southbound, downhill, just beyond sharp curve seen in image 19, towards very sharp corner to the right.



Image 21: Traveling southbound, downhill, towards very sharp corner to the right seen in image 20.

Dip to curve 20 foot edge to edge - many problems here in winter.



Image 22a: Traveling southbound. Road curves uphill to left just beyond public access point to Tanner Lake.



Image 22b: Facing northbound towards public access point to Tanner Lake, crest of hill, road is 18 feet wide, edge to edge.




Image 22c: Facing northbound towards public access point to Tanner Lake, crest of hill, road is 18 feet wide, edge to edge.



Image 23: Traveling southbound. Just south of public access point to Tanner Lake. Road curves sharp to left.



Image 24: Traveling southbound.



Image 25: Traveling southbound towards very sharp corner to the left.



Image 26: Traveling southbound towards entrance of Denmar pit. Long sharp corner to right.



Image 27: Traveling southbound towards entrance of Denmar pit - in long sharp corner to right seen in image 26.



Image 28: Traveling southbound towards entrance of Denmar pit - still in long sharp corner to right seen in image 26 - 27.



Image 29: **Now traveling northbound from Hwy 17**, uphill, curves to right at residential driveway on left at crest of hill.



Image 30: Traveling northbound nearing crest of hill seen in image 29.



Image 31: Traveling northbound, snakes to the right then quickly left.



Image 32: Traveling northbound, sharp to the right.



Image 33: Traveling northbound, sharp to the right.



Image 34: Traveling northbound, sharp to the right, towards Lafond Rd. and West Nipissing Rod and Gun club entrance.



Image 35: Traveling northbound, long curve to the left.



Image 36: Traveling northbound.



Image 37: Traveling northbound. Sharp curve to left.



Image 38: Traveling northbound. Curve to right towards residential driveway.



Image 39: Traveling northbound. Sharp right just beyond residential driveway.



Image 40: Traveling northbound, uphill, curves left just beyond access road.



Image 41: Traveling northbound, downhill, curves sharp right.



Image 42: Traveling northbound, curves sharp left, just south of Denmark pit main entrance.



Image 43: Traveling northbound, looking south at sharp left seen in image 42, just south of Denmark pit main entrance.



Image 44: Looking northbound, uphill, at the same spot seen in image 43, just south of Denmark pit main entrance.



Image 45: Traveling northbound, uphill, sharp left, at main entrance of Denmark pit.



Image 46: Traveling northbound, at main entrance of Denmark pit. Road continues northward toward long sharp corner to the left, seen in images 26 - 28.